



Missouri



American Recovery and Reinvestment Act

52 DoD Projects (\$ 72.4M) Completed or Under Way by August 31, 2009

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Training Barracks Building 1028-Replace and Restore All Components to Advanced Individual Training Standard Barracks	Army	Fort Leonard Wood	10,168
Training Barracks Building 816-Replace and Restore All Components to Advanced Individual Training Standard Barracks	Army	Fort Leonard Wood	10,168
Training Barracks Building 817-Replace and Restore All Components to Advanced Individual Training Standard Barracks	Army	Fort Leonard Wood	10,168
Training Barracks Building 818-Replace and Restore All Components to Advanced Individual Training Standard Barracks	Army	Fort Leonard Wood	10,168
Dining Facility Building 820-Replace and Restore All Components	Army	Fort Leonard Wood	6,500
Ops Building 822-Replace and Restore All Components to Advanced Individual Training Standard BN Ops	Army	Fort Leonard Wood	2,828
Asphalt Requirements	Army	Fort Leonard Wood	2,000
Replace Boilers - 600, 700, & 800 Areas	Army	Fort Leonard Wood	2,000
Repair Primary and Secondary Digester at sewage treatment plant	Army	Fort Leonard Wood	1,958
Replace Railroad Bridge, 14.7	Army	Fort Leonard Wood	1,700
Provide Air Conditioning System for Gyms - 600, 700, & 800 Areas	Army	Fort Leonard Wood	1,500
Replace High Temp Boiler #1, B-1021	Army	Fort Leonard Wood	1,500

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Replace High Temp Boiler #2, B-1021	Army	Fort Leonard Wood	1,500
Replace Air Conditioning Systems in Specker Admin Facs	Army	Fort Leonard Wood	1,200
Repair Taxiway Alphas Pavement	Army	Fort Leonard Wood	523
Upgrade/Replace Fire Alarm Equipment	Army	Fort Leonard Wood	500
Replace High Temp Heat Sys W/Boilers, B-5400	Army	Fort Leonard Wood	350
Replace Obsolete Boilers, B-749/837	Army	Fort Leonard Wood	350
Replace Cooling Tower @ B1021	Army	Fort Leonard Wood	250
Upgrade Interior of Chapels, B-637/843	Army	Fort Leonard Wood	223
Replace 2 Cast Iron Section Boilers, B-826	Army	Fort Leonard Wood	213
Repair Exterior of Chapels, B-450/637/742/843/1712	Army	Fort Leonard Wood	200
Repair Leaking Boilers	Army	Fort Leonard Wood	200
Replace Old Am-150 Boilers, B-2030	Army	Fort Leonard Wood	160
Replace Sectional Hot Water Boiler, B-1000	Army	Fort Leonard Wood	125
Repair Asphalt Road @Lora	Army	Fort Leonard Wood	100
Upgrade BACNET digital Controls	Army	Fort Leonard Wood	40

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair/upgrade Barracks (Building 1232) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1240) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1241) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1244) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1259) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1260) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1274) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1275) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1276) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Repair/upgrade Barracks (Building 1278) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	Fort Leonard Wood	180
Replace Warehouse Lights	Army National Guard	Ike Skelton Jefferson City Training Site	70
Repair/upgrade Barracks (Building B468) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	MTA Camp Clark Nevada	160
Repair/upgrade Barracks (Building B469) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	MTA Camp Clark Nevada	160
Repair/upgrade Barracks (Building B470) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	MTA Camp Clark Nevada	160
Repair/upgrade Barracks (Building B471) to Current Fire Protection, Energy Controls, Restrooms Standards	Army National Guard	MTA Camp Clark Nevada	160

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Const Radiant Heat, Multi Buildings 121, 154, 159, 169, 709, 1706	Air Force	Whiteman AFB	643
Repair Flightline Road: A-10 Ramp Ph 1	Air Force	Whiteman AFB	489
Repair Inefficient Ventilation Controls, 105 Facs	Air Force	Whiteman AFB	486
Repair Roof, Hangar 27	Air Force	Whiteman AFB	340
Repair Roof: Mid Section- Base Whse Building 115	Air Force	Whiteman AFB	264
Repair Roof, Hangar 91	Air Force	Whiteman AFB	235
Repair Low Roof, B-2 Docks 3, 5, 7 (Multi)	Air Force	Whiteman AFB	217
Repair Hot Water: Acft Cor Con B27- Nrg	Air Force	Whiteman AFB	216
Repair Roof, B-2 Dock 11 (B 5062)	Air Force	Whiteman AFB	214
Repair Roof, B-2 Dock 12 (B 5063)	Air Force	Whiteman AFB	214